

Control charts

Process control for Feed production

Content

- Introduction Pre-Mervo
- Introduction Kwaliteitsdienst
- Measuring in process
 - Variations
 - Analyses instrument
- Control chart principles
- Control charts practical results
- Proces optimization

Premix company since 1969



- Cooperative
- Independent
- Turn over € 75 000 000
- Premix coverage of 4 million tons of feed
- Market leader in The Netherlands
- European sales scope
- Partnership with Komponenta



Product lines



- MERVIT Premixes (65 ktons)
 - 54% complete
 - 23% additional
 - 23% mineral feed
- Mervo Best (140 ktons)
- Raw materials (amino acids etc.)
- Laboratory Services



Content

- Introduction Pre-Mervo
- Introduction Kwaliteitsdienst
- Measuring in process
 - Variations
 - Analyses instrument
- Control chart principles
- Control charts practical results
- Proces optimization


Kwaliteitsdienst

- Samples: 17 000 in 2009
- Chemical analyses
 - Weender
 - Elements
 - Fatty acids
 - Additives
- Mycotoxins
- Amino acids
- Vitamins
- Microbiology
- NIRS
 - measurements
 - production and maintenance of calibrations for feed mills

Content

- Introduction Pre-Mervo
- Introduction Kwaliteitsdienst
- Measuring in process
 - Variations
 - Analyses instrument
- Control chart principles
- Control charts practical results
- Proces optimization

Process basics



Measuring in process



- Raw materials
 - Variation in raw material content
 - Variation in sampling
 - Variation in analyses
- Finished products
 - Variation in raw material content
 - Variation in dosing
 - Variation in blending
 - Variation in sampling
 - Variation in analyses

Analyses instruments




- Laboratory
- Reference method
- Limited amount of samples
- Slow, results to late
- Low frequency
- NIRS
- Derived method
- High amount of samples
- Fast, results in time
- High frequency

Content

- Introduction Pre-Mervo
- Introduction Kwaliteitsdienst
- Measuring in process
 - Variations
 - Analyses instrument
- Control chart principles
- Control charts practical results
- Proces optimization

Plotting data




20-20-2010

Pre-Mervo Kwaliteitsdienst


12

Plotting data



Plotting data

Result plot with 2S and 3S boundaries and prediction



Measuring strategy

- All raw materials
 - All suppliers
- Selected finished products
 - Frequent production
 - Covering all major raw materials

Action control cards




- Exceeding 3S 1x
- Exceeding 2S 2x
- One side of expected value > 11x

Content

- Introduction Pre-Mervo
- Introduction Kwaliteitsdienst
- Measuring in process
 - Variations
 - Analyses instrument
- Control chart principles
- Control charts practical results
- Proces optimization

Piglet feed




20-20-2010

Pre-Mervo Kwaliteitsdienst

18

Piglet feed




20-20-2010

Pre-Mervo Kwaliteitsdienst

19

Piglet feed




20-20-2010

Pre-Mervo Kwaliteitsdienst

20

Piglet feed




20-20-2010

Pre-Mervo Kwaliteitsdienst

21

Piglet feed




20-20-2010

Pre-Mervo Kwaliteitsdienst

22

Piglet feed



20-20-2010

Pre-Mervo Kwaliteitsdienst

23

Front page


Controlekaart			Biggenvoer	Versie:	1			
Meting	Datum	Kode	Omschrijving	Vocht	Beoordeling Ruw eiwit Proces	Beoorde Ruw Vet Proces	Beoorde Ruwe celstof Proces	
1	11-6-2007	6041-44.spc	runnr134144	103 < X	GOED	184 > X	GOED	47 > X
2	22-6-2007	biva 1.spc		115 =	GOED	176 > X	GOED	44 < X
3	22-6-2007	biva 2.spc		113 < X	GOED	168 < X	GOED	45 < X
4	22-6-2007	biva 3.spc		113 < X	GOED	162 < X	GOED	43 < X
5	27-6-2007	w49 (QS4).spc	6111-41 134650	107 < X	GOED	170 < X	GOED	49 > X
6	4-7-2007	wp42 .spc	6361-44 56487	110 < X	GOED	184 > X	GOED	46 =
7	4-7-2007	wp38.spc	6231-32 56488	121 > X	GOED	174 > X	GOED	51 > X
8	11-7-2007	wp31.spc	6211-33 56635	111 < X	GOED	180 > X	GOED	49 > X
9	19-7-2007	deurzen.spc		130 > X	GOED	164 < X	GOED	43 < X
10	19-7-2007	deurzen .spc		130 > X	GOED	161 < X	GOED	42 < X
11	25-7-2007	wp47.spc	6005-1 56753	106 < X	GOED	175 > X	GOED	45 < X
12	25-7-2007	wp47..spc	6005-1 56753	106 < X	GOED	175 > X	GOED	47 > X
13	25-7-2007	nir3.spc	6111-41 56836	113 < X	GOED	159 < X	GOED	47 > X
14	15-8-2007	wp51.spc	6005-2 57253	120 > X	GOED	167 < X	GOED	44 < X
15	19-9-2007	wp64 .spc	6031 57877	116 > X	GOED	178 > X	GOED	41 < X
16	19-9-2007	w75 .spc	7102-6 137299	120 > X	GOED	172 =	GOED	41 < X
17	2-10-2007	wp-60-.spc	6111-4-857979	118 > X	GOED	181 > X	GOED	43 < X
18	10-10-2007	ep-61.spc	biggen-058256	119 > X	GOED	185 > X	GOED	45 < X
19	23-10-2007	w83.spc	7102-6-138101	114 < X	GOED	173 > X	GOED	42 < X
20	23-10-2007	yklyn.spc	6211-38	124 > X	GOED	178 > X	GOED	42 < X
21	5-11-2007	wp69.spc	biggen-6041-46	116 > X	GOED	182 > X	GOED	43 < X
22	5-11-2007	yklyn.-spc.spc	biggen-6111-4	113 < X	GOED	171 < X	GOED	46 =
23	7-11-2007	w89.spc	biggen-6111-47	126 > X	GOED	179 > X	GOED	44 < X
24	14-11-2007	wp-73.spc	biggen-6211-38	126 > X	GOED	169 < X	GOED	44 < X
25	16-11-2007	havens.spc		127 > X	GOED	186 > X	GOED	46 =
26	16-11-2007	havens1.spc		127 > X	GOED	179 > X	GOED	46 =
27	16-11-2007	havens2.spc		125 > X	GOED	184 > X	GOED	43 < X
28	27-11-2007	w93.spc	139277	125 > X	GOED	170 < X	GOED	32 < -3s
29	28-11-2007	wp-76.spc	59139	120 > X	GOED	159 < X	GOED	41 < X
30	2-1-2008	weender..spc	24558	109 < X	GOED	173 > X	GOED	40 < X

Front page




Controlekaart		Biggenvoer		Versie: 1											
Meting	Datum	Kode	Omschrijving	Vocht	Beoordeling Ruw eiwit Proces	Beoorde Ruw Vet Proces	Beoorde Ruwe celstof Proces	Beoorde As Proces	Beoerd Zetmeel Proces	Beoordeling Proces					
1	11-6-2007	6041-44.spc	runnr134144	103 < X	GOED	184 > X	GOED	51 > X	GOED	47 > X	GOED	58 > X	GOED	378 < X	GOED
2	22-6-2007	biva 1.spc		115 =	GOED	176 > X	GOED	31 < X	GOED	44 > X	GOED	56 > X	GOED	428 > X	GOED
3	22-6-2007	biva 2.spc		113 < X	GOED	168 < X	GOED	33 < X	GOED	45 < X	GOED	53 < X	GOED	428 > X	GOED
4	22-6-2007	biva 3.spc		113 < X	GOED	162 < X	GOED	31 < X	GOED	43 < X	GOED	52 < X	GOED	437 > X	GOED
5	27-6-2007	w49 (QS4).spc	6111-41 134650	107 < X	GOED	170 < X	GOED	47 > X	GOED	49 > X	GOED	56 > X	GOED	413 < X	GOED
6	4-7-2007	wp42.spc	6361-44 56487	110 < X	GOED	184 > X	GOED	48 > X	GOED	46 =	GOED	55 =	GOED	373 < X	GOED
7	4-7-2007	wp38.spc	6231-32 56488	121 > X	GOED	174 > X	GOED	47 > X	GOED	51 > X	GOED	55 =	GOED	400 < X	GOED
8	11-7-2007	wp31.spc	6211-33 56635	111 < X	GOED	180 > X	GOED	43 > X	GOED	49 > X	GOED	56 > X	GOED	413 < X	GOED
9	19-7-2007	deurzen.spc		130 > X	GOED	164 < X	GOED	16 < X	GOED	43 < X	GOED	54 < X	GOED	435 > X	GOED
10	19-7-2007	deurzen.spc		130 > X	GOED	161 < X	GOED	18 < X	GOED	42 < X	GOED	53 < X	GOED	435 > X	GOED
11	25-7-2007	wp47.spc	6005-1 56753	106 < X	GOED	175 > X	GOED	50 > X	GOED	45 < X	GOED	55 =	GOED	407 < X	GOED
12	25-7-2007	wp47.spc	6005-1 56753	106 < X	GOED	175 > X	GOED	49 > X	GOED	47 > X	GOED	58 > X	GOED	415 > X	GOED
13	25-7-2007	nir3.spc	6111-41 56836	113 < X	GOED	159 < X	GOED	43 > X	GOED	47 > X	GOED	56 > X	GOED	416 > X	GOED
14	15-8-2007	wp51.spc	6005-2 57253	120 > X	GOED	167 < X	GOED	36 =	GOED	44 < X	GOED	53 < X	GOED	428 > X	GOED
15	19-9-2007	wp64.spc	6031 57877	116 > X	GOED	178 > X	GOED	45 > X	GOED	41 < X	GOED	61 < X	GOED	410 < X	GOED
16	19-9-2007	w75.spc	7102-6 137299	120 > X	GOED	172 =	GOED	43 > X	GOED	41 < X	GOED	63 < X	GOED	407 < X	GOED
17	2-10-2007	wp60.spc	6111-4-857979	118 > X	GOED	181 > X	GOED	45 > X	GOED	43 < X	GOED	66 > X	GOED	400 < X	GOED
18	10-10-2007	ep-61.spc	biggen-058256	119 > X	GOED	185 > X	GOED	47 > X	GOED	45 < X	GOED	65 > X	GOED	391 < X	GOED
19	23-10-2007	w83.spc	7102-6-138101	114 < X	GOED	173 > X	GOED	43 > X	GOED	42 < X	GOED	69 > +2s	GOED	417 > X	GOED
20	23-10-2007	yklyn.spc	6211-38	124 > X	GOED	178 > X	GOED	38 > X	GOED	42 < X	GOED	65 > X	GOED	413 < X	GOED
21	5-11-2007	wp69.spc	biggen-6041-46	116 > X	GOED	182 > X	GOED	42 > X	GOED	43 < X	GOED	64 =	GOED	389 < X	GOED
22	5-11-2007	yklyn.spc	biggen-6111-4	113 < X	GOED	171 > X	GOED	42 > X	GOED	46 =	GOED	64 =	GOED	413 < X	GOED
23	7-11-2007	w89.spc	biggen-6111-47	126 > X	GOED	179 > X	GOED	44 > X	GOED	44 < X	GOED	64 =	GOED	393 < X	GOED
24	14-11-2007	wp73.spc		126 > X	GOED	169 < X	GOED	41 > X	GOED	44 < X	GOED	63 < X	GOED	407 < X	GOED
25	16-11-2007	havenas.spc		127 > X	GOED	186 > X	GOED	51 > X	AKTIE !	46 =	GOED	68 > X	GOED	359 < -2s	GOED
26	16-11-2007	havenas1.spc		127 > X	GOED	179 > X	GOED	47 > X	AKTIE !	46 =	GOED	65 > X	GOED	369 < X	GOED
27	16-11-2007	havenas2.spc		125 > X	GOED	184 > X	GOED	48 > X	AKTIE !	43 < X	GOED	63 < X	GOED	373 < X	GOED
28	27-11-2007	w93.spc	139277	125 > X	GOED	170 < X	GOED	41 > X	AKTIE !	32 < -3s	AKTIE !	66 > X	GOED	406 < X	GOED
29	28-11-2007	wp76.spc	59139	120 > X	GOED	159 < X	GOED	31 < X	GOED	41 < X	GOED	59 < -2s	GOED	442 > X	GOED
30	2-1-2008	weerdeer..spc	24558	109 < X	GOED	173 > X	GOED	37 > X	GOED	40 < X	GOED	65 > X	GOED	429 > X	GOED
31	2-1-2008	wp79.spc	06051-48-59376	110 < X	GOED	179 > X	GOED	46 > X	GOED	47 > X	GOED	65 > X	GOED	419 > X	GOED
32	8-1-2008	yklyn--.spc	140365-6111-48	122 > X	GOED	180 > X	GOED	43 > X	GOED	39 < X	GOED	62 < X	GOED	403 < X	GOED
33	8-1-2008	wo52.spc	-59160	129 > X	GOED	173 < X	GOED	29 < X	GOED	44 =	GOED	64 =	GOED	430 > X	GOED
34	16-1-2008	weo4.spc	mo21064	114 < X	GOED	167 < X	GOED	34 < X	GOED	41 < X	GOED	62 < X	GOED	443 > X	GOED
35	22-1-2008	wep5.spc	60106	97 < -2s	GOED	175 > X	GOED	53 > X	GOED	50 > X	GOED	69 > +2s	GOED	423 > X	GOED
36	22-1-2008	wey4.spc	-7462	126 > X	GOED	163 < X	GOED	45 > X	GOED	44 =	GOED	63 < X	GOED	406 < X	GOED
37	30-1-2008	w101.spc	140905-7102-7	121 > X	GOED	168 < X	GOED	32 < X	GOED	40 < X	GOED	63 < X	GOED	438 > X	GOED
38	13-2-2008	wep9.spc	060254-06111-48	110 < X	GOED	181 > X	GOED	52 > X	GOED	44 =	GOED	65 > X	GOED	401 < X	GOED
39	13-2-2008	wep3.spc	060520-07102-8	106 < X	GOED	172 < X	GOED	32 < X	GOED	34 < -3s	AKTIE !	62 < X	GOED	450 > X	GOED
40	3-3-2008	wep13.spc	060673-6211-39	113 < X	GOED	165 < X	GOED	37 < X	GOED	45 > X	GOED	63 < X	GOED	442 > X	GOED
41	5-3-2008	wep11.spc	60843-7102-9	127 > X	GOED	161 > X	GOED	22 < -2s	GOED	40 < X	GOED	59 < -2s	GOED	451 > X	GOED
42	12-3-2008	wep17.spc	060697-7102-9	115 < X	GOED	174 =	GOED	31 < X	GOED	41 < X	GOED	63 < X	GOED	444 > X	GOED
43	2-4-2008	wey25.spc	142633-6111-54	112 < X	GOED	178 > X	GOED	54 > X	GOED	43 < X	GOED	66 > X	GOED	388 < X	GOED
44	2-4-2008	wep18.spc	061274-6111-51	121 > X	GOED	169 < X	GOED	49 > X	GOED	40 < X	GOED	61 < X	GOED	393 < X	GOED
45	28-4-2008	wep23.spc	61746-6111-55	107 < X	GOED	176 > X	GOED	42 > X	GOED	38 < X	GOED	64 =	GOED	416 > X	GOED
46	28-4-2008	wep26.spc	6211-41	110 > X	GOED	174 =	GOED	41 =	GOED	43 < X	GOED	64 =	GOED	427 > X	GOED
47	13-5-2008	wey36.spc	143595-7102-10	113 < X	GOED	164 < X	GOED	31 < X	GOED	44 =	GOED	63 < X	GOED	439 > X	GOED
48	13-5-2008	wey37.spc	143596=6211-41	101 < X	GOED	170 < X	GOED	41 =	GOED	45 > X	GOED	63 < X	GOED	429 > X	GOED
49	20-5-2008	wep28.spc	7102-10-062115	89 < -3s	AKTIE !	164 < X	GOED	43 > X	GOED	48 > X	GOED	65 > X	GOED	443 > X	GOED
50	20-5-2008	wep30.spc	6111-55-062108	90 < -3s	AKTIE !	189 > X	GOED	50 > X	GOED	38 < X	GOED	69 > +2s	GOED	415 > X	GOED
51	20-5-2008	weo37.spc	300618-29-mo2703	83 < -3s	AKTIE !	171 < X	GOED	36 < X	GOED	41 < X	GOED	67 > X	GOED	472 > +2s	GOED
52	28-5-2008	wey44.spc	6041-51-144127	105 < X	GOED	179 > X	GOED	47 > X	GOED	41 < X	GOED	64 =	GOED	389 < X	GOED
53	25-6-2008	wey49.spc	6983-5-144727	100 < -2s	GOED	161 < X	GOED	47 > X	GOED	43 < X	GOED	61 < X	GOED	435 > X	GOED
54	9-2-2008	wep36.spc	421412-063901	113 < X	GOED	164 < X	GOED	39 < X	GOED	45 > X	GOED	63 < X	GOED	442 > X	GOED
55	9-9-2008	wey64.spc	201312-5	117 =	GOED	170 < X	GOED	27 < X	GOED	48 > X	GOED	62 < X	GOED	455 > +2s	GOED
56	30-9-2008	wel39.spc	201512-1-63233	114 < X	GOED	167 < X	GOED	47 > X	GOED	44 =	GOED	62 < X	GOED	420 > X	GOED
57	6-10-2008	wep55.spc	421312-3-64241	115 < X	GOED	170 < X	GOED	34 < X	GOED	44 =	GOED	64 =	GOED	449 > X	GOED
58	6-10-2008	wep48.spc	201412-6-64316	127 > X	GOED	160 < X	GOED	29 < X	GOED	45 > X	GOED	61 < X	GOED	454 > +2s	GOED
59	6-10-2008	wep41.spc	421312-64313	123 > X	GOED	160 < X	GOED	32 < X	GOED	44 =	GOED	62 < X	GOED	449 > X	GOED
60	7-10-2008	wep46.spc	421412-064437	124 > X	GOED	174 =	GOED	39 < X	GOED	40 < X	GOED	60 < X	GOED	419 > X	GOED

Raw materials




Finished product



Content

- Introduction Pre-Mervo
- Introduction Kwaliteitsdienst
- Measuring in process
 - Variations
 - Analyses instrument
- Control chart principles
- Control charts practical results
- Proces optimization

Proces optimization



Optimization

- Short term
 - Raw materials
 - Supplier selection
 - Refusing bad lots
 - Finished products
 - Production failures
- Long term
 - Adjustment of matrix values of raw materials to guarantee delivery of promised feed value.



Thank you for your attention

ERROR: undefined
OFFENDING COMMAND: Peter

STACK:

```
(13)
>Title
()
/Subject
(D:20101203151252+01'00')
/ModDate
()
/Keywords
(PDFCreator Version 0.9.5)
/Creator
(D:20101203151252+01'00')
/CreationDate
(dusica.ivanov)
/Author
-mark-
```